Rack Monitor Layout RM for Short.






Figure 2a.



RM Connections PS



The center two Rack Monitors chassis are used for power supply monitoring.

The Right (typically) RM is used for thermometry.